Kit Instructions

XL7W Wedge Stand

Revision Record

Issue	Date	Remarks
A	Apr 2018	First Issue
B	Dec 2019	Updated terminology for USB with type C connector
C	Aug 2020	Added Wedge Stand dimensions

XL7W Wedge Stand

This kit provides a wedge stand for the NCR XL7W (5907) Display.

Kit Contents

XL7W Wedge Stand Cover
497-0520161

M4x8 Flat Head Steel Black Oxide
006-8617801

XL7W Wedge Stand
497-0519867

CCP-72984

Dimensions

45 mm
(1.77 in.)

123 mm
(4.84 in.)

26.00º

102 mm
(4.02 in.)

4.8 mm
(0.19 in.)

107 mm
(4.21 in.)

8 mm
(0.31 in.)

10 mm
(0.39 in.)

4 mm
(0.16 in.)

75 mm
(2.95 in.)

23.7 mm
(0.93 in.)

10.5 mm
(0.41 in.)

50 mm
(1.97 in.)

19.6 mm
(0.77 in.)

Ø4.5 mm (x4)

Ø12 mm (x2)

11 mm
(0.43 in.)

75 mm
(2.95 in.)

Ø6 mm (x2)

CCP-79568

Installation Procedure

1. Connect the USB end of the Display Cable to the back of the Display. Tighten the thumbscrew.

   Note: Avoid overtightening the thumbscrew by turning it only until the silver knurled portion touches the black plastic overmold. Overtightening the thumbscrew damages the connector on the board.

CCP-72934

2. Remove the Cover from the Wedge Stand.

   a. Swing the Cover upward to detach. The Cover has a snap fit connection on the bottom.

   b. Pull Cover in the direction shown to unlatch.


CCP-72985

3. Install the Wedge Stand on the back of the Display (4 screws).

CCP-72986

4. Route the Cable through the slot between the tabs and make sure the Cable is behind the tab.

CCP-72987

5. Reinstall the Wedge Stand Cover.

   a. Insert the tabs of the Cover into the Wedge Stand.

   b. Swing the Cover down until it latches into place.

Wedge Stand Cover

CCP-72988

6. Connect the Display Cable to the host terminal.