Kit Instructions

XL10W Wedge Stand

5910–K030
Issue D

Revision Record

Issue	Date	Remarks
A	July 2018	First Issue
B	Dec 2019	Updated terminology for USB with type C connector
C	May 2020	Updated cable routing for XL10 USB model
D	Sep 2020	Added Wedge Stand dimensions, and cable routing for Display Port and HD Model

XL10W Wedge Stand

This kit provides a wedge stand for the NCR XL10W (5910) Display.

Kit Contents

XL10W Wedge Stand Cover
497-0520175

M4x8 Flat Head Steel Black Oxide
006-8617801

XL10W Wedge Stand
497-0519892

CCP-72966

Dimensions

70 mm
(2.76 in.)

172 mm
(6.77 in.)

26.05º

154 mm
(6.06 in.)

CCP-79567

Installation Procedure

1. Remove the Cover from the Wedge Stand.

   a. Swing the Cover upward to detach. The Cover has a snap fit connection on the bottom.

   b. Pull Cover in the direction shown to unlatch.

Wedge Stand Cover

CCP-72967

2. Connect the Display Cables and route them as shown.

Display Port Model

Display Power Cable | Audio Cable | Display Port Cable

CCP-72980

Display Port and HD Model

Display Power Cable | Audio Cable | HD Video Cable

CCP-79559

USB Model

USB Cable

CCP-79043

3. Install the Wedge Stand on the back of the Display (4 screws).


CCP-72968

4. Route the Cables through the slot between the tabs and make sure the Cables are behind the tabs.

CCP-72982

5. Reinstall the Wedge Stand Cover.

    a.   Insert the tabs of the Cover into the Wedge Stand.

    b.   Swing the Cover down until it latches into place.

Wedge Stand Cover

CCP-72969

6. Connect the Display Cable(s) to the host terminal.