Kit Instructions

Power Adapter

ONCR

5915–K100 Issue B The product described in this document is a licensed product of NCR Corporation.

NCR is a registered trademark of NCR Corporation. NCR RealPOS is a trademark of NCR Corporation in the United States and/or other countries. Other product names mentioned in this publication may be trademarks or registered trademarks of their respective companies and are hereby acknowledged.

The terms HDMI and HDMI High-Definition Multimedia Interface, and the HDMI Logo are trademarks or registered trademarks of HDMI Licensing LLC in the United States and other countries.

Where creation of derivative works, modifications or copies of this NCR copyrighted documentation is permitted under the terms and conditions of an agreement you have with NCR, NCR's copyright notice must be included.

It is the policy of NCR Corporation (NCR) to improve products as new technology, components, software, and firmware become available. NCR, therefore, reserves the right to change specifications without prior notice.

All features, functions, and operations described herein may not be marketed by NCR in all parts of the world. In some instances, photographs are of equipment prototypes. Therefore, before using this document, consult with your NCR representative or NCR office for information that is applicable and current.

To maintain the quality of our publications, we need your comments on the accuracy, clarity, organization, and value of this book. Please use the link below to send your comments.

EMail: FD230036@ncr.com

Copyright © 2020–2024 By NCR Corporation Global Headquarters 864 Spring St NW Atlanta, GA 30308 U.S.A. All Rights Reserved

Table of Contents

<u>12V DC Power Adapter</u>

Kit Contents	1
Installation Procedure	2

Revision Record


Issue	Date	Remarks
А	Nov 2020	First Issue
В	Mar 2024	Updated Part Number from 497-0521670 to 497-0528586

12V DC Power Adapter

This kit provides a Power Adapter for the following displays:

- XL10W Display (5910)
- XL15 Display (5915)
- XL15W Display (5916)
- X-Series Display (5968/5985)

Kit Contents



* Items marked with an asterisk are not called out on the image.

Installation Procedure

- 1. Connect the External Power Cable to the display Power connector.
- 2. Connect the other end of the External Power Cable to the USB connector on the host terminal.
- 3. Connect the Power Adapter DC Cable to the External Power Cable (middle of cable).
- 4. Connect the AC Power Cord to the Power Adapter and an AC outlet.

