


SpacePole Display Mount

Kit Instructions



1668-K104 Issue D

Copyright and Trademark Information

The products described in this document are copyrighted works of NCR Voyix Corporation.

NCR Voyix 1668 is a trademark of NCR Voyix Corporation in the United States and/or other countries. Other product names mentioned in this publication may be trademarks or registered trademarks of their respective companies and are hereby acknowledged.

Where creation of derivative works, modifications or copies of this NCR Voyix copyrighted documentation is permitted under the terms and conditions of an agreement you have with NCR Voyix, NCR Voyix's copyright notice must be included.

Disclaimer:

It is the policy of NCR Voyix Corporation to improve products as technology, components, software and firmware become available. NCR Voyix therefore reserves the right to change specifications without prior notice.

All features, functions and operations described herein may not be marketed by NCR Voyix in all parts of the world. In some instances, photographs are of equipment prototypes.

Therefore, before using this document, consult with your NCR Voyix representative or NCR Voyix office for information that is applicable and current.

© 2017-2025

By NCR Voyix Corporation

Atlanta, Georgia, USA

All Rights Reserved

Table of Contents

SpacePole Display Mount	5
Kit Contents	5
Dimensions	5
Installation Procedure	6


Revision Record

Publication issue	Date	Description of change
А	Apr 2017	First issue
В	Dec 2017	Added pole dimensions
С	Sep 2020	Updated Kit Contents illustration Added XL Display
D	Sep 2025	Updated to NCR Voyix brand

SpacePole Display Mount


This kit provides the components to install a SpacePole Display Mount.

Kit Contents




CCP-79569

Dimensions




Installation Procedure

1. For countertop installation, drill four holes for the mounting bolts in the desired location. Use the SpacePole Mount base as a template for locating the holes. Install the SpacePole Display Mount and secure with screws (4) or bolts (4) included in the hardware pack or with your preferred fasteners.



2. Install the Flange Cover.




3. Attach the POS display to the SpacePole arm by sliding the bracket tabs into the head slots.





Note

For XL Displays, connect the cables to the back of the display before mounting the display on the bracket.




4. Tighten the (2) thumbscrews at the bottom of the bracket to secure the display. For XL Displays, tighten the (2) thumbscrews and install (4) M4x12 screws to secure the display.






5. Route the cables from the display down the SpacePole Mount and out of the integration tray or the countertop.



6. Install the Cable Clip to secure the cables.



7. Add the integration tray cover.

